



View

Leak Detection | Pipe Condition

Administration | Maintenance


Project: Loveland
20 Loggers

Area: east derby hill
0 Loggers

Measurement Period: Mar 2, 2018

dB

Correlations | Logger Noise | Events



	Quality	Logger 1	Logger 2	Distan...
↑	70%	510 172	510 173	30.1 ft
↑	50%	510 159	510 160	0.0 ft
●	40%	510 158	510 172	549.8 ft
●	40%	510 159	510 172	317.0 ft