OAHP1403 Rev. 9/98

COLORADO CULTURAL RESOURCE SURVEY

Architectural Inventory Form

Official eligibility determination			
(OAHP use only)			
Date	Initials		
	Determined Eligible- NR		
	Determined Not Eligible- NR		
	Determined Eligible- SR		
	Determined Not Eligible- SR		
	Need Data		
	Contributes to eligible NR District		
	Noncontributing to eligible NR District		

I. IDENTIFICATION

1. Resource number: 5LR.14721 Parcel number(s):

2. Temporary resource no.: N/A 9513414021

County: Larimer
 City: Loveland

5. Historic building name: Cloyd House, Fay House, Johnson House, Weickum House

Current building name: Dinsmore House
 Building address: 733 E. 5th Street
 Owner name and Mathew J. Dinsmore

address: P. O. Box 7772

Loveland, CO 80537



National Register eligibility assessment: State Register eligibility assessment: Loveland Historic Landmark eligibility assessment: Historic District eligibility assessment: Not Individually Eligible Not Individually Eligible Eligible Contributing

II. GEOGRAPHIC INFORMATION

9. P.M. 6th Township 5N Range 69W

SW ¼ of SW ¼ of NW ¼ of SE ¼ of section 13

10. UTM reference (NAD 27)

Zone 13: 494290 mE 4471575 mN

11. USGS quad name: Loveland, Colorado

Year: 1962; Photorevised 1984 Map scale: 7.5

12. Legal Description: "LOTS 21 & 22, BLK 2, AMD, GIFFORD GOSS ADD, LOV"

Addition: **Gifford-Goss** Year of Addition: **1906**

13. Boundary Description and Justification: This legally defined parcel encompasses, but does not exceed, the land historically associated with this property.

III. ARCHITECTURAL DESCRIPTION

14. Building plan (footprint, shape): Rectangular Plan15. Dimensions in feet: 1144 square feet

16. Number of stories: One

17. Primary external wall material(s): Wood / Horizontal Siding

18. Roof configuration: Gabled Roof / Front Gabled Roof
19. Primary external roof material: Asphalt Roof / Composition Roof

20. Special features: Porch, Chimneys, Decorative Shingles, Fence

21. General architectural description:

This Bungalow-type dwelling features a basic rectangular-shaped plan that measures 44' N-S x 26' E-W. It is supported by a painted green poured concrete foundation, and its exterior walls are clad with painted gold color horizontal wood siding. The roof is a moderately-pitched front gable, covered with brown asphalt composition shingles. Painted gold color rafter ends, with a fascia board, are exposed beneath the widely-overhanging eaves. Painted brown variegated wood shingles, and decorative purlins with knee braces appear in the upper gable ends. A vent opening within a diamond-shaped motif is centered in the façade's upper gable end. A brown brick fireplace chimney is on the west-facing wall, and a brown brick chimney is on the ridge.

The façade faces south toward 5th Street. A painted white glass-in-wood-frame door enters near the center of the façade from an open full-width porch that measures 7' N-S x 26' E-W, and that is recessed under the main gable roof. Approached by three concrete steps, the porch features a concrete floor, a painted gold and burgundy open wood railing, and painted gold pedestals and tapered piers. A painted white wood-paneled door, with horizontally-oriented upper sash lights, and covered by a painted green wood storm door, enters the west end of the north-facing wall from a concrete stoop. The home's windows have painted white wood frames, painted burgundy wood surrounds, and metal exterior storm

windows. The west-facing wall contains a slightly-projecting rectangular-shaped bay, with three oneover-one double-hung sash windows covered by a metal awning. Two small horizontally-oriented 5light, ribbon-style windows flank the fireplace chimney, also in the west-facing wall. The north-facing wall contains a set of paired 6-light windows and a non-historic 1-beside-1 horizontal sliding window. Elsewhere, windows are single and paired one-over-one double-hung sash.

22. Architectural style/building type: Bungalow

23. Landscaping or special setting features:

This property is located on the north side of East 5th Street in the primarily residential neighborhood east of downtown Loveland. The former St. Paul's Evangelical Lutheran Church (5LR.6688) is adjacent to the east at the corner of East 5th Street and Pierce Avenue. The landscape features planted grass front and back yards, with narrow side yards along the east and west sides of the house. The backyard is enclosed by an older woven wire fence. A wide grass strip with a deciduous tree is between the public sidewalk and the street curb. A concrete-paved driveway extends from the street along the west side of the house to a single-stall garage. A gravel alley is behind the property to the north.

24. Associated buildings, features, or objects:

Garage

A one-story, single-stall, garage that measures 18' N-S x 12' E-W is located northwest of the dwelling. Supported by a poured concrete foundation and floor, its exterior walls are clad with painted gold color horizontal wood siding with 1" x 4" corner boards. The garage is covered by a moderately-pitched front gable roof, with brown asphalt composition shingles laid over 1x wood decking and 2x wood rafters. The rafter ends are painted gold, and are exposed beneath the eaves. The south-facing wall contains a set of paired vertical wood plank doors, side-hinged with metal strap hinges. These doors open onto the driveway that extends along the west side of the house to East 5th Street. The east-facing wall contains a single-entry vertical wood plank door that accesses the garage from the backyard.

IV. ARCHITECTURAL HISTORY

25. Date of Construction: Estimate: 1919 Actual:

Source of information: Larimer County Real Estate Appraisal Card, Sanborn Insurance

maps, Loveland city directories.

26. Architect: Unknown

Source of information: N/A

27. Builder/Contractor: Unknown

Source of information: N/A

28. Original owner: Unknown

Source of information: N/A

- 29. Construction history (include description and dates of major additions, alterations, or demolitions): Larimer County Assessor records list 1919 as this dwelling's year of construction. The property's address, 733 E. 5th Street, does not appear in the 1919 Loveland city directory; however, it is listed in the next available, 1922 directory. The dwelling and garage are both depicted on the August 1927 Loveland Sanborn Insurance maps. This block is not depicted on earlier Sanborn maps. There are no additions, and only minor exterior alterations, to the dwelling's original construction.
- 30. Original Location: Yes Date of move(s): N/A

V. HISTORICAL ASSOCIATIONS

31. Original use(s): Domestic / Single Dwelling
32. Intermediate use(s): Domestic / Single Dwelling
33. Current use(s): Domestic / Single Dwelling

34 Site Type: Building

35. Historical background:

John W. and Addie M. Cloyd, who are listed at this address in the 1922 Loveland city directory, are this home's earliest known residents. The Cloyds do not appear in subsequent directories, however, as William G. and Caroline F. Wagner next occupied the home, from the mid-1920s to the early 1930s.

The son of Charles and Lizzie (Pauls) Wagner, William G. Wagner was born in Franklin County, Missouri on June 29, 1873. The daughter of German immigrants Henry and Johanna Faessler, Caroline was also born in Franklin County, Missouri on November 8, 1873. William and Caroline were married in 1893, and lived in St. Louis until moving to Loveland in the years between 1910 and 1920. Five children were born to the couple over a span of more than twenty years. The 1920 U. S. federal census lists the Wagner family as residing on Harrison Avenue in Loveland, including William and Caroline, a daughter, Adele, age 11, an infant son, Arnold, age ten months, and Johanna Faessler, Caroline's widowed mother. Census records and city directories indicate that the Wagners were farmers, perhaps growing sugar beets for the Great Western Sugar Company. They moved from Harrison Avenue to this house on East 5th Street, circa 1924, where they lived until the early 1930s. William Wagner died in Loveland on December 17, 1944 at the age of 71. Caroline passed away on October 10, 1949, at the age of 75. They are interred in the Loveland Burial Park Cemetery.

733 E. 5th Street was next owned and occupied by Henry and Minnie Fay, during the early 1930s. The son of George and Emma Fay, Henry was born in Larimer County on June 9, 1892. He grew up in the Fort Collins area, and served in World War I during the late-1910s. On March 15, 1922, he was married to Miss Minnie Willbrandt, who had been born in Kansas in 1886. A daughter named Betty was born to the couple circa 1927. The 1930 U. S. federal census lists the Fay family as living on Logan Avenue in

Loveland. At that time, the family consisted of Henry and Minnie, their daughter Betty, and Minnie's unmarried sister, Mary Willbrandt, who worked as a dressmaker. Henry Wagner worked as a foreman for the Great Western Sugar Company until his untimely death, at age forty on September 9, 1932. (The circumstances surrounding his death are unknown). Minnie Wagner continued to live in this house for until shortly before her own death which occurred in 1940, at age 54.

Horace W. and Virginia E. Robinson next occupied this home from the late 1930s through the war years of the early 1940s. Horace worked as an accountant and served as Loveland's city auditor. The Robinsons had a daughter, named Judith, who was born circa 1935.

W. Fred and Lillian Johnson next owned and lived in this home from the late 1940s until the late 1950s. Fred Johnson worked as a salesman at Huston's Men's Shop prior to his retirement circa 1954. He was born on April 28, 1883, and died on April 10, 1957 at the age of 74. Following her husband's death, Lillian Johnson continued to live in this house for a few more years, until moving elsewhere in Loveland, circa 1960. Lillian's maiden name is unknown; however, she was born on April 27, 1863, and died on April 10, 1967. Mr. and Mrs. Johnson are interred in Loveland's Burial Park Cemetery.

This home's next long-term owners were the Jake and Edna Weickum family, who were associated with the property from the early 1960s to the late 1980s. The Weickum family included Jake, who worked as a mechanic for the Great Western Sugar Company, Edna, and a son named Randy, born circa 1959.

In more recent years, the property has evidently served primarily as a rental. Larimer County Assessor records indicate it has been owned by Mathew J. Dinsmore since 2008.

36. Sources of information:

A Guide to Historic Loveland (Loveland Museum and Gallery, 1996).

Larimer County Assessor Online Property Records: https://www.larimer.org/assessor/search#/property/ (Larimer County) "Real Estate Appraisal Card." On file at the Loveland Museum Gallery.

City of Loveland building permit files, on file in the Development Services Department, Building Division, 410 E. 5th Street, Loveland, CO.

Loveland City Directories.

Loveland's Historic Downtown: A Guide to the Buildings (Loveland Museum and Gallery, 2001). Newspaper Articles (arranged chronologically)

"John W. Cloyd Dies Suddenly at Home Sunday Noon." *Loveland Reporter Herald*, February 19, 1923, p. 1.

"Johnson." (Lillian Johnson obituary) *Loveland Daily Reporter Herald*, April 12, 1967, p. 3.

Sanborn Fire Insurance maps of Loveland, dated June 1886, December 1890, September 1893,

November 1900, March, 1906, May 1911, April 1918, August 1927, July 1937, and September 1946.

VI. SIGNIFICANCE

37. Local landmark designation: No Date of designation: N/A

Designating authority: N/A

- 38. Applicable National Register Criteria:
 - A. Associated with events that have made a significant contribution to the broad pattern of our history;
 - B. Associated with the lives of persons significant in our past;
 - C. Embodies the distinctive characteristics of a type, period, or method of construction, or represents the work of a master, or that possess high artistic values, or represents a significant and distinguishable entity whose components may lack individual distinction; or
 - D. Has yielded, or may be likely to yield, information important in history or prehistory.

Qualifies under Criteria Considerations A through G (see Manual)

✓ Does not meet any of the above National Register criteria

38. A Loveland Standards for Designation

✓	Architectural	Exemplifies specific elements of an architectural style or period
	Architectural	Is an example of the work of an architect or builder who is recognized for
		expertise nationally, statewide, regionally, or locally
	Architectural	Demonstrates superior craftsmanship or high artistic value
	Architectural	Represents an innovation in construction, materials, or design
	Architectural	Represents a built environment of a group of people in an era of history
	Architectural	Exhibits a pattern or grouping of elements representing at least one of
		the above criteria
	Architectural	Is a significant historic remodel
	Social/cultural	Is a site of an historic event that had an effect upon society
✓	Social/cultural	Exemplifies the cultural, political, economic, or social heritage of the
		community

Social/cultural Is associated with a notable person(s) or the work of a notable person(s)

Geographic/environmental Enhances sense of identity of the community

community

39. Area(s) of significance: Architecture
40. Period of significance: 1919 - 1970
41. Level of significance: Local

42. Statement of significance:

This house is architecturally significant as an intact, representative, Bungalow type dwelling dating from the late-1910s. It is also historically significant, to a modest extent, for its association with residential development in Loveland through the end of the 1960s. The property's level of historical and architectural significance is not to the extent that it qualifies for individual listing in the National Register of Historic Places or in the State Register of Historic Properties. The property, however, may regarded as eligible for local landmark designation by the City of Loveland, and it would qualify as a contributing resource within a locally-designated or National Register historic district.

43. Assessment of historic physical integrity related to significance:

This property displays an overall high level of physical integrity, relative to the seven aspects of integrity as defined by the National Park Service and the Colorado Historical Society - setting, location, design, materials, workmanship, feeling and association. There are no additions and no notable exterior alterations to the dwelling's original construction. The property's original single-stall garage also remains intact, and enhances the integrity of setting.

VII. NATIONAL REGISTER ELIGIBILITY ASSESSMENT

44. National Register eligibility assessment: Not Individually Eligible State Register eligibility assessment: Not Individually Eligible

Local Landmark eligibility assessment: Eligible

45. Is there National Register district potential? Yes

Discuss: Historic properties in this primarily residential neighborhood east of downtown Loveland have the potential to form a historic district. More broadly, Loveland's east side neighborhoods, lying west and southwest of the former Great Western Sugar Company property have the potential to form one or more historic districts. This area is generally bordered by Jefferson Street on the west, 4th Street on the south, 13th Street on the north, and Monroe and Pierce Avenues on the east.

If there is N.R. district potential, is this building contributing or noncontributing? Contributing

46. If the building is in an existing N.R. district, is it contributing or noncontributing? N/A

VIII. RECORDING INFORMATION

47. Photograph numbers: CD #1; Images 57-62

CD filed at: City of Loveland

Development Services Department

410 E. 5th Street Loveland, CO 80537

48. Report title: Germans from Russia and the Great Western Sugar Company: A Survey of Historical Properties (Loveland CLG project CO-19-10006)

49. Date(s): May 12, 2020


50. Recorder(s): Carl McWilliams

51. Organization: Cultural Resource Historians


52. Address: 1607 Dogwood Court, Fort Collins, CO 80525

53. Phone number(s): (970) 493-5270

Sketch Map



Location Map





CD 1, Image 57, View to North, of the dwelling



CD 1, Image 58, View to Northwest, of the dwelling



CD 1, Image 59, View to Northeast, of the dwelling



CD 1, Image 60, View to South, of the dwelling



CD 1, Image 61, View to Southwest, of the garage



CD 1, Image 62, View to North, of the garage